


EYEBALL SPRING HANGER BOLTS




TAKE A LOOK
RIGHT NOW, DRIVERS,
TO SEE IF THE **SPRING
HANGER BOLTS** ON
YOUR M917A1 DUMP TRUCK
HAVE BEEN INSTALLED
CORRECTLY.


If the **bolt head** is visible on the outside of the spring hanger (you can see it without crawling underneath the truck), the bolt is installed **correctly**.



If the **threaded end** is visible on the outside of the spring hanger, the bolt is installed **incorrectly**.



It may have already caused some tire damage because the tire rubbed against the bolt end when the truck was heavily loaded.



Let your mechanic know if the threaded end is visible so the problem can be corrected. Let him know if there is tire damage, too.

HEMTT Parts Update

Note these changes to your HEMTT's TM 9-2320-279-24P. The water pump, Item 1 in Fig 63, is now NSN 2930-01-354-9202. The pintle assembly, Item 1 in Fig 238, was changed to NSN 2540-01-475-9206. The front (double-lipped) axle seal, Item 11 in Fig 181, is NSN 5330-01-236-2179.